

2006100130001





FIG. 1

200610100909001



52

57

55

58

60


70

51

64

66

F16.2







FIG. 3

200570 009090078





Fig. 4

2002T0" 0090900T



50

101




14



Fig. 5

66

14

66





200610"0030900T








Fig. 3

File 9





2004-01-09 09:00

52








FIG. 10









FIG. 12





2006103600309007

56

57




Fig. 13

50

66

64

67

53

2006T0-0090900T





FIG. 14



FIG. 15



2006FO-00909007






FIG. 15(A)



200670-00909001





42a 42b 44 46







FIG 17